




The impact on the seabed weakened & caused 2 major bends on the Riser, besides minor bending & twisting.



BK Lim - 12 Aug 2010  
([hydrocomgeo@gmail.com](mailto:hydrocomgeo@gmail.com))

Well A

720 ft

S20BC